## U. S. PUBLIC LAND SURVEY MONUMENT RECORD


INSTRUCTIONS:

This record shall show the location of the corner and shall include all of the following nine elements (a through i).

(a) Identify the corner by reference to the U.S. public land survey system.

O = Corner monument restored.

SE Corner of Section 20, Town 11 North, Range 21 East, Town of Saukville, OZAUKEE County, Wisconsin.



3E COR SEC 20-11-21

(b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

Measured East, using compass, 2640 feet from S  $\frac{1}{4}$  corner of Section 20. Fell 20 feet West and 50 feet South of fences found. Very thick brush and swampy.

Found old fence (barbed wire) North, East and West. Cast Aluminum Bernsten Monument Cap on a  $1\frac{1}{2}$ "x5' Iron Pipe placed at junction of old fences.

- (c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.) Describe witness monuments.
- (d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.

NOTES ALL WITNESS MONUMENTS ARE I"IRON PIPES LEFTE! UP.

CORNER MONUMENT IS A CAST ALUMINUM BERNSTEN MON. CAP ON I'M" x 5' IRON PIPE LEFT ±1' UP MOUNDED UP WITH CONCRETE SURROUNDE BY THREE BRANCHES IN THE SHAPE OF A TRIANGLE.

B' TAMARACK
2' NW
IPS


12" TAMARACK
BLAZED

10' SOUTH

o = Corner monument restored.

SE Corner of Section 20, Town
Il North, Range 21 East, Town
of Saukville, OZAUKEE County,

Wisconsin.



(b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

Measured East, using compass, 2640 feet from S  $\frac{1}{4}$  corner of Section 20. Fell 20 feet West and 50 feet South of fences found. Very thick brush and swampy.


Found old fence (barbed wire) North, East and West. Cast Aluminum Bernsten Monument Cap on a  $1\frac{1}{2}$ "x5' Iron Pipe placed at junction of old fences.

- (c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.)

  Describe witness monuments.
- (d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.

NOTE: ALL WITNESS MONUMENTS ARE I"IRON PIPES LEFT ! I'UP.

CORNER MONUMENT IS A CAST ALUMINUM BERNSTEN MON. CAP ON I'' 5 IRON PIPE LEFT ±1' UP MOUNDED UP WITH CONCRETE SURROUNDED BY THREE BRANCHES IN THE SHAPE OF A TRIANGLE.



(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

No known re-establishment. Last known monumentation was the original government survey.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Obliterated evidence location,

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

No.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Obliterated evidence location.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

No.

Ronald A. Weis S-1215

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Konald A. Wis Signature

Dec. 29 1888



Affix Land:Surveyor Seal

RONALD A VVEIS S-1215 WEST BEND,